10/633247



**PATENT** 

I hereby certify that on the date specified below, this correspondence is being deposited with the United States Postal Service as first-class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Theodore T. Pekny

Attorney Docket No.: 500118.02

Patent No. : US 6,754,111 B2

Serial No.

: 10/633,247

Issue Date: June 22, 2004

Filed

: August 1, 2003

Title

: DUAL BANDGAP VOLTAGE REFERENCE SYSTEM AND METHOD FOR REDUCING CURRENT CONSUMPTION DURING A STANDBY MODE OF OPERATION AND FOR PROVIDING REFERENCE STABILITY DURING AN

ACTIVE MODE OF OPERATION

### REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate MAY 1 8 2005

of Correction

Sir:

A Certificate of Correction under 35 U.S.C. § 254 is respectfully requested for the above-identified patent in order to correct Patent and Trademark Office errors made during the printing of the patent. The changes in the patent needed to correct the errors are as follows:

Column, Line	Reads	Should Read
Column 3, Line 26	"providing a highly stable"	providing highly stable
Column 4, Lines 60	"CEI#signal"	CEI# signal
and 62		
Column 4, Line 64	"with a substantially no"	with substantially no

Column 5, Line 13	"standby bandgap, voltage"	standby bandgap voltage
Column 5, Line 39	"the band gap switching"	the bandgap switching
Column 6, Line 11	"operated during the standby"	operates during the standby
Column 6, Line 21	"reference 304, to"	reference 304 to
Column 6, Lines 32 and 36	"WL1-N using the"	WL1-WLN using the
Column 6, Line 44	"generating about VX voltage"	generating VX voltage
Column 7, Line 3	"accessing row of memory"	accessing rows of memory
Column 7, Line 16	"transfer operation"	transfer operations
Column 7, Lines 56- 57	"standby band gap voltage"	standby bandgap voltage
Column 8, Line 31		
<b>-</b>	"and OE#in combination"	and OE# in combination
Column 8, Line 41	"and OE#in combination"  "404 develops applies signals"	and OE# in combination404 applies signals
•	"404 develops applies	
Column 8, Line 41	"404 develops applies signals"	404 applies signals

The above errors for which correction is requested under 35 U.S.C. § 254 were made in the printing of the patent. The errors are considered sufficiently important to justify the processing of a Certificate of Correction under 35 U.S.C. § 254. A Form PTO-1050, in duplicate, is enclosed herewith.

The Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 50-1266. A duplicate copy of this sheet is enclosed.

Favorable consideration of this Request is respectfully requested.

Respectfully submitted,

Date: ///ay 10, 2005

By: Edward W. Bulchis, Reg. No. 26,847

Customer No. 27,076
Dorsey & Whitney LLP
1420 Fifth Avenue, Suite 3400
Seattle, WA 98101
(206) 903-8785
Attorney for Applicant(s)


EWB:tdk

Enclosures:

Postcard Form PTO-1050 (+ copy)

500118.02 req cert correct





I hereby certify that on the date specified below, this correspondence is being deposited with the United States Postal Service as first-class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

May 10, 2005

Alexandra Beggs

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant : Theodore T. Pekny

Attorney Docket No.: 500118.02

Patent No.: US 6,754,111 B2

Serial No. : 10/633,247

Issue Date: June 22, 2004

Filed

: August 1, 2003

Title

: DUAL BANDGAP VOLTAGE REFERENCE SYSTEM AND METHOD FOR REDUCING CURRENT CONSUMPTION DURING A STANDBY MODE OF OPERATION AND FOR PROVIDING REFERENCE STABILITY DURING AN

ACTIVE MODE OF OPERATION

### REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

A Certificate of Correction under 35 U.S.C. § 254 is respectfully requested for the above-identified patent in order to correct Patent and Trademark Office errors made during the printing of the patent. The changes in the patent needed to correct the errors are as follows:

Column, Line	Reads	Should Read
Column 3, Line 26	"providing a highly stable"	providing highly stable
Column 4, Lines 60	"CEI#signal"	CEI# signal
and 62		
Column 4, Line 64	"with a substantially no"	with substantially no

Column 5, Line 13	"standby bandgap, voltage"	standby bandgap voltage
Column 5, Line 39	"the band gap switching"	the bandgap switching
Column 6, Line 11	"operated during the standby"	operates during the standby
Column 6, Line 21	"reference 304, to"	reference 304 to
Column 6, Lines 32 and 36	"WL1-N using the"	WL1-WLN using the
Column 6, Line 44	"generating about VX voltage"	generating VX voltage
Column 7, Line 3	"accessing row of memory"	accessing rows of memory
Column 7, Line 16	"transfer operation"	transfer operations
Column 7 Lines 56	44 11 1 1	4 11 1 . 1
Column 7, Lines 56-57	"standby band gap voltage"	standby bandgap voltage
ŕ	•	and OE# in combination
57	gap voltage"	
57 Column 8, Line 31	gap voltage" "and OE#in combination" "404 develops applies	and OE# in combination
57 Column 8, Line 31 Column 8, Line 41	gap voltage" "and OE#in combination" "404 develops applies signals"	and OE# in combination404 applies signals

The above errors for which correction is requested under 35 U.S.C. § 254 were made in the printing of the patent. The errors are considered sufficiently important to justify the processing of a Certificate of Correction under 35 U.S.C. § 254. A Form PTO-1050, in duplicate, is enclosed herewith.

The Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 50-1266. A duplicate copy of this sheet is enclosed.

Favorable consideration of this Request is respectfully requested.

Respectfully submitted,

Date: May 10, 2005

Bv:

Edward W. Bulchis, Reg. No. 26,847

Customer No. 27,076
Dorsey & Whitney LLP
1420 Fifth Avenue, Suite 3400
Seattle, WA 98101
(206) 903-8785
Attorney for Applicant(s)

EWB:tdk

Enclosures:

Postcard Form PTO-1050 (+ copy)

500118.02 req cert correct

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,754,111 B2

DATED

June 22, 2004

INVENTOR(S)

Theodore T. Pekny

It is certified that errors appear in the above identified patent and that said Letters Patent is hereby corrected as shown below:

Column, Line	Reads	Should Read
Column 3, Line 26	"providing a highly stable"	providing highly stable-
Column 4, Lines 60 and 62	"CEI#signal"	CEI# signal
Column 4, Line 64	"with a substantially no"	with substantially no
Column 5, Line 13	"standby bandgap, voltage"	standby bandgap voltage
Column 5, Line 39	"the band gap switching"	the bandgap switching
Column 6, Line 11	"operated during the standby"	operates during the standby
Column 6, Line 21	"reference 304, to"	reference 304 to
Column 6, Lines 32 and 36	"WL1-N using the"	WL1-WLN using the
Column 6, Line 44	"generating about VX voltage"	generating VX voltage
Column 7, Line 3	"accessing row of memory"	accessing rows of memory
Column 7, Line 16	"transfer operation"	transfer operations
Column 7, Lines 56-57	"standby band gap voltage"	standby bandgap voltage
Column 8, Line 31	"and OE#in combination"	and OE# in combination
Column 8, Line 41	"404 develops applies signals"	404 applies signals
Column 9, Line 3	"440a, 44b to access"	440a, 440b to access
Column 10, Line 30	"a digital cameras,"	digital cameras,

Column 14, Line 13	"having desired value;"	having a desired value;
1		

MAILING ADDRESS OF SENDER:

Patent No. <u>US 6,754,111 B2</u>

DORSEY & WHITNEY LLP 1420 Fifth Avenue, Suite 3400 Seattle, Washington 98101 No. add'l. copies @ .30 per page

FORM PTO-1050 (REV. 3-82)

500118.02 PTO 1050

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,754,111 B2

DATED

June 22, 2004

INVENTOR(S)

Theodore T. Pekny

It is certified that errors appear in the above identified patent and that said Letters Patent is hereby corrected as shown below:

Column, Line	Reads	Should Read
Column 3, Line 26	"providing a highly stable"	providing highly stable-
Column 4, Lines 60 and 62	"CEI#signal"	CEI# signal
Column 4, Line 64	"with a substantially no"	with substantially no
Column 5, Line 13	"standby bandgap, voltage"	standby bandgap voltage
Column 5, Line 39	"the band gap switching"	the bandgap switching
Column 6, Line 11	"operated during the standby"	operates during the standby
Column 6, Line 21	"reference 304, to"	reference 304 to
Column 6, Lines 32 and 36	"WL1-N using the"	WL1-WLN using the
Column 6, Line 44	"generating about VX voltage"	generating VX voltage
Column 7, Line 3	"accessing row of memory"	accessing rows of memory
Column 7, Line 16	"transfer operation"	transfer operations
Column 7, Lines 56-57	"standby band	standby bandgap
	gap voltage"	voltage
Column 8, Line 31	"and OE#in combination"	and OE# in combination
Column 8, Line 41	"404 develops applies signals"	404 applies signals
Column 9, Line 3	"440a, 44b to access"	440a, 440b to access
Column 10, Line 30	"a digital cameras,"	digital cameras,

MAY 2 3 2005.

MAY 3 3 LOO

Column 14, Line 13	"having desired value;"	having a desired value;

MAILING ADDRESS OF SENDER:

DORSEY & WHITNEY LLP 1420 Fifth Avenue, Suite 3400 Seattle, Washington 98101

FORM PTO-1050 (REV. 3-82)

500118.02 PTO 1050

Patent No. <u>US 6,754,111 B2</u>

No. add'l. copies

@ .30 per page